

1/16

FIG. 1A




FIG. 1B





FIG. 2



2/16

FIG. 3





FIG. 4



3/16

FIG. 5





FIG. 6



09881235.061401  
FOI-90-5218860

4/16

FIG. 7




FIG. 8






FIG. 9



6/16


FIG. 10



BEST AVAILABLE COPY

7/16

FIG. 11



BEST AVAILABLE COPY


[illegible]



9/16

FOOTNOTES

FIG. 13



10/16

FIG. 14A




FIG. 14B





FIG. 14C




BEST AVAILABLE COPY

09881235-061401

11/16


FOH790" SE2F8860

FIG. 15



BEST AVAILABLE COPY


FIG. 16




30D




FIG. 18



PRIOR ART  
 FIG. 19A



PRIOR ART  
 FIG. 19B



PRIOR ART  
 FIG. 20




FIG. 21

